


Diagram illustrating the correct method for tightening a nut. The left side shows a nut being tightened with a wrench, with a callout indicating a torque of  $\leq 40 \text{ Nm}$ . The right side shows a nut being tightened with a screwdriver, which is incorrect.





6720812227-02.1T

**A** 7738330165,  
7738330166

22 mm  
28 mm

**B** 7738330167  
7738330168  
7738330169  
7738330170  
7738330171

Rp 3/4...2

6720812227-03.3T

*Fig. 5*




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19